

WILDLAND GLOVE

WILDLAND FIREFIGHTING



How to Properly Measure Hand Length

Place a sheet of paper on a flat surface.
Place your right hand palm down on the piece of paper with fingers together and the hand and arm in a straight line. Extend the thumb away from the palm as far as possible.
Mark the paper at the tip of the third, or middle, finger.
Mark the paper in the notch at the base of the thumb, where the thumb joins the wrist.
Square a straight line between the two marked locations.
Measure to the nearest 1/8 inch (3 mm).

How to Properly Measure Hand Circumference

Place a measuring tape on a flat surface with the numerals facing downward.
Place your right hand palm down and fingers together in the middle of the tape so that the tape can pass straight across the metacarpal knuckles.
Wrap the tape around to the back of the hand until the ends meet, the tape should not be tight, but comfortably snug around the knuckles.
Measure to the nearest 1/8 inch (3 mm).

Range for Hand Length Range for Hand Circumference

| Glove Size | Range for Hand Length | | Range for Hand Circumference | |
|------------------|-----------------------|-------------|------------------------------|-------------|
| | Inches | Centimeters | Inches | Centimeters |
| Extra Small (XS) | 6.40-6.79 | 16.25-17.25 | 6.40-7.97 | 16.25-20.25 |
| Small (S) | 6.79-7.19 | 17.25-18.25 | 6.79-8.37 | 17.25-21.25 |
| Medium (M) | 7.19-7.58 | 18.25-19.25 | 7.19-8.76 | 18.25-22.25 |
| Large (L) | 7.58-7.97 | 19.25-20.25 | 7.58-9.15 | 19.25-23.25 |
| Extra-Large (XL) | 7.97-8.37 | 20.25-21.25 | 7.97-9.55 | 20.25-24.25 |

Please contact Inside Sales, or your Regional Sales Manager, with any questions.

